

GENERAL USE



Foam Depressant 631 will effectively depress foam in the following industrial processes:

- Cleaning compounds
- Soap and detergent solutions
- Adhesive manufacturing
- Glue manufacturing
- Abrasive manufacturing
- Dyeing and finishing processes
- Starch solutions
- Textile chemicals

FEATURES AND BENEFITS

- Silicone based defoamer
- Water dilutable
- Effective
- Efficient
- Low odor
- Broad range of use

DIRECTIONS FOR USE

Use procedure

Before addition of **Foam Depressant 631** to your process, dilute 1 part of product to 10 parts water.

Then add this solution to the foaming product, somewhere in the range of 15 ppm to 100 ppm, i.e., approximately 2 to 12 fluid ounces per 100 gallons of solution to be defoamed.

FOAM DEPRESSANT 631

WATER-DILUTABLE DEFOAMER

PHYSICAL PROPERTIES

Appearance	Opaque white liquid
Odor	Mild, sweet
pH	7.0 - 8.5
Freezing Point	Greater than 32°F
Boiling Point	About 212°F
Flash Point (TCC)	None to boil
Relative Density	1.00
Auto-Ignition Temperature	Not applicable
Water Solubility	Dispersible
Viscosity	1000 to 5000 CP at room temperature

INCOMPATIBILITY

Strong oxidizing materials.

WAREHOUSING PRECAUTIONS

Keep container tightly closed when not in use. Use containment devices to prevent uncontrolled spills. Do not store near strong acids or bases. Do not store in direct sunlight. Avoid storing above 120°F (49°C).

AVAILABLE SIZES

4 X 1 gallon Case

FIRST AID MEASURES

If in eyes: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. If eye irritation persists or develops: Get medical advice or attention. Penetone recommends that after any eye exposure a physician be seen immediately.

If swallowed: Rinse mouth. Call a poison center, doctor, physician or other competent medical authority if you feel unwell.

If inhaled: Remove person to fresh air and keep comfortable for breathing. Call a poison center, doctor, physician or other competent medical authority if you feel unwell.

If on skin: Wash with plenty of water or a mild soap. Take off contaminated clothing and wash it before reuse. If skin irritation occurs: Get medical advice or attention.

PERSONAL PROTECTION Security equipment



WHMIS Not classified

IMPORTANT: Before using **FOAM DEPRESSANT 631**, always be sure to read and follow precautions and directions for use appearing on the product container label and on the safety data sheet (S.D.S).



CARLSTADT

700 Gotham Parkway
Carlstadt, NJ 07072
Tel.: 201-567-3000
Toll free: 1-800-631-1652

MONTREAL

10,900 Secant Street
Anjou, QC H1J 1S5
Tel.: 514-355-4660
Toll free : 1-800-361-8927

EDMONTON

11411-160 Street
Edmonton, Alberta T5M 3T7
Tel.: 780-454-3919
Toll free: 1-866-454-3919

United States
www.penetone.com

Canada
www.westpenetone.com