

GENERAL USE



Slix will cut through the toughest petroleum-based soils, such as crude, bunker C and rolling oils and thick gear box lubes. In particular, cement floors and pump pads can be easily cleaned and whitened to a pleasing appearance.

Slix can also be used for the heaviest soils in locker rooms, machinery, transportation equipment and oil storage equipment. **Slix** combines the highest quality detergents with special wetting agents to form a fast-acting cleaner that has hundreds of uses.

FEATURES AND BENEFITS

- Phosphate free
- Biodegradable
- Free of petroleum solvents
- No flash point
- No odor
- Easier to treat than phosphated cleaners
- Restores appearance of floors and equipment

DIRECTIONS FOR USE

Use procedures

Floors Mix 1:10 to 1:20 with water, mop or brush, rinse. Or use at 1:30 to 1:40 in automatic floor scrubbers.

Heavily soiled floors Apply undiluted, brush with stiff bristle brush, rinse.

Machinery Mix 1:10 to 1:30, spray on, brush if necessary, rinse.

Steam cleaning Mix 1:20 to 1:40. Pre-wet surface.

Transportation equipment Mix 1:20. Wash from bottom up. Rinse from top down.

SLIX

HEAVY DUTY DEGREASER

PHYSICAL PROPERTIES

Appearance	Clear liquid
Odor	Mild
pH	About 12
Freezing Point	About 32°F
Boiling Point	About 212°F
Flash Point (TCC)	Not applicable
Relative Density	1.05
Auto-Ignition Temperature	Not applicable
Water Solubility	Complete
Viscosity	100-200 CP at room temperature

INCOMPATIBILITY
Strong acids.

WAREHOUSING PRECAUTIONS
Store locked up. Do not store in direct sunlight. Avoid storing above 120°F (49°C).

APPROVALS
USDA

AVAILABLE SIZES
5 gallon Pail
50 gallon Drum

FIRST AID MEASURES

If in eyes: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Immediately call a poison center, doctor, physician or other competent medical authority for medical advice. Penetone recommends that after any eye exposure a physician be seen immediately.

If swallowed: Rinse mouth. **DO NOT INDUCE VOMITING.** Immediately call a poison center, doctor, physician or other competent medical authority for medical advice.

If inhaled: Remove person to fresh air and keep comfortable for breathing. Immediately call a local Poison Control Center, physician, or other competent medical authority for medical advice.

If on skin (or hair): Take off immediately all contaminated clothing. Rinse skin with water or shower. A mild soap may be used to wash skin. Wash contaminated clothing before reuse. Immediately call a local Poison Control Center, doctor, physician or other competent medical authority for medical advice.

PERSONAL PROTECTION Security equipment



WHMIS



IMPORTANT: Before using **SLIX**, always be sure to read and follow precautions and directions for use appearing on the product container label and on the safety data sheet (S.D.S).



CARLSTADT
700 Gotham Parkway
Carlstadt, NJ 07072
Tel.: 201-567-3000
Toll free: 1-800-631-1652

MONTREAL
10,900 Secant Street
Anjou, QC H1J 1S5
Tel.: 514-355-4660
Toll free: 1-800-361-8927

EDMONTON
11411-160 Street
Edmonton, Alberta T5M 3T7
Tel.: 780-454-3919
Toll free: 1-866-454-3919

United States
www.penetone.com

Canada
www.westpenetone.com