

GENERAL USE



Penblitz 422H is a heavy duty liquid alkaline cleaner designed for use on a multitude of tough soils in many different areas. Stubborn greases, tars, and oils can be removed without damage to most surfaces. Rinsing will leave a film and streak free surface.

FEATURES AND BENEFITS

- Controlled foaming
- Safe on most painted surfaces
- Biodegradable
- Concentrated
- Benefits
- Won't streak or spot
- Free rinsing
- Penetrates soils
- Economical to use

DIRECTIONS FOR USE

Use procedure

Concrete and unpainted floors Mix **Penblitz 422H** 1:1 to 1:20 with water for general cleaning. Apply with mop or sprayer. Scrub if necessary. Rinse with water.

Mill floors and oil cellars Mix **Penblitz 422H** 1:1 to 1:10 with water depending on severity of soil. Apply evenly. Brush if necessary. Rinse with water.

High pressure spray washing Mix **Penblitz 422H** 1:10 to 1:50 with water. Use the lowest pressure that will do the job effectively, holding nozzle close to surface to insure maximum impingement. Rinse with water.

Heavy duty steam cleaning Mix **Penblitz 422H** 1:40 with water. Steam or water rinse.

Extra heavy duty steam cleaning Mix **Penblitz 422H** 1:20 with water. Where possible, pre-wet the entire surface prior to steam cleaning. Use the lowest pressure that will do the job effectively, holding nozzle close to surface to insure maximum impingement. Steam or water rinse.

Note **Penblitz 422H** is safe on brass, copper and steel. It will have a mild etching effect on aluminum.

PENBLITZ 422H

HEAVY DUTY ALKALINE CLEANER

PHYSICAL PROPERTIES

| | |
|---------------------------|------------------------------------|
| Appearance | Clear purple liquid |
| Odor | Mild |
| pH | >13 |
| Freezing Point | About 32°F |
| Boiling Point | About 212°F |
| Flash Point (TCC) | Not applicable |
| Relative Density | 1.08 |
| Auto-Ignition Temperature | Not applicable |
| Water Solubility | Soluble |
| Viscosity | Less than 5 CP at room temperature |

INCOMPATIBILITY

Strong acids. Soft metals such as aluminum, brass, bronze, copper, lead, tin, zinc or other alkali sensitive metals or alloys.

WAREHOUSING PRECAUTIONS

Store locked up. Store in corrosive resistant container. Plastic is recommended. Keep container tightly closed when not in use.
Do not store near strong bases.
Do not store in direct sunlight.
Avoid storing above 120°F (49°C).

AVAILABLE SIZES

5 gallon Pail

55 gallon Drum

345 gallon Tote

FIRST AID MEASURES

If in eyes: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Immediately call a poison center, doctor, physician or other competent medical authority for medical advice. Penetone recommends that after any eye exposure a physician be seen immediately.

If swallowed: Rinse mouth. DO NOT INDUCE VOMITING. Immediately call a poison center, doctor, physician or other competent medical authority for medical advice.

If inhaled: Remove person to fresh air and keep comfortable for breathing. Immediately call a local Poison Control Center, physician, or other competent medical authority for medical advice.

If on skin (or hair): Take off immediately all contaminated clothing. Rinse skin with water or shower. A mild soap may be used to wash skin. Wash contaminated clothing before reuse. Immediately call a local Poison Control Center, doctor, physician or other competent medical authority for medical advice.

PERSONAL PROTECTION Security equipment



WHMIS



IMPORTANT: Before using **PENBLITZ 422H**, always be sure to read and follow precautions and directions for use appearing on the product container label and on the safety data sheet (S.D.S).



CLIFTON

125 Kingsland Avenue
Clifton, NJ 07014
Tel.: 201-567-3000
Toll free: 1-800-631-1652

MONTREAL

10,900 Secant Street
Anjou, QC H1J 1S5
Tel.: 514-355-4660
Toll free: 1-800-361-8927

EDMONTON

11411-160 Street
Edmonton, Alberta T5M 3T7
Tel.: 780-454-3919
Toll free: 1-866-454-3919

United States
www.penetone.com

Canada
www.westpenetone.com