

GENERAL USE



Wedac is an acid containing detergent that cleans, derusts and descales. **Wedac** contains a stable inhibitor which provides effective protection on most metals and many other surfaces. **Wedac** can be used at any strength in dip, brush or wipe-on methods.

Wedac has rapid wetting and penetrating action providing faster rust and corrosion removal than other commonly used acids. Stable for use over a wide range of temperatures, **Wedac's** special inhibitor does not precipitate out and become inactive even after large amounts of rust and corrosion have been dissolved.

FEATURES AND BENEFITS

- Highly concentrated
- Very low vapor pressure
- Eliminates butyl cellosolve, a VOC found in similar products
- Little or no odor
- Contains no muriatic acid
- Free rinsing
- Very cost effective
- Safer to personnel & the environment
- Reduces reporting
- Reduces waste generation and disposal costs
- Pleasant to use

DIRECTIONS FOR USE

Use procedure	Wedac may be applied by tank immersion, circulation, brush or wipe-on methods.
Concentration	5-25% by volume with water.
Temperature	160-180°F.
Rinsing	After cleaning, always rinse with water. At high temperatures solutions are low foaming, facilitating rinsing.
Note	Wedac solutions are not recommended for cleaning galvanized, chrome, nickel or tin plated metals.

WEDAC[®]

ACID CLEANER AND DESCALER

PHYSICAL PROPERTIES

Appearance	Pink liquid
Odor	Mild
pH	<1
Freezing Point	About 25°F
Boiling Point	About 212°F
Flash Point (TCC)	Not applicable
Relative Density	1.38
Auto-Ignition Temperature	Not applicable
Water Solubility	Complete
Viscosity	10-30 CP at room temperature

INCOMPATIBILITY

Strong bases.

WAREHOUSING PRECAUTIONS

Store locked up. Store in corrosive resistant container. Plastic is recommended. Keep container tightly closed when not in use. Do not store in direct sunlight. Avoid storing above 120°F (49°C).

AVAILABLE SIZES

4 X 1 gallon Case

50 gallon Drum

FIRST AID MEASURES

If in eyes: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Immediately call a local Poison Control Center, doctor, physician or other competent medical authority for medical advice. Penetone recommends that after any eye exposure a physician be seen immediately.

If swallowed: Rinse mouth. DO NOT INDUCE VOMITING. Immediately call a poison center, doctor, physician or other competent medical authority for medical advice.

If inhaled: Remove person to fresh air and keep comfortable for breathing. Immediately call a local Poison Control Center, physician, or other competent medical authority for medical advice.

If on skin (or hair): Take off immediately all contaminated clothing. Rinse skin with water or shower. A mild soap may be used to wash skin. Wash contaminated clothing before reuse. Immediately call a local Poison Control Center, doctor, physician or other competent medical authority for medical advice.

PERSONAL PROTECTION Security equipment



WHMIS



IMPORTANT: Before using **WEDAC**, always be sure to read and follow precautions and directions for use appearing on the product container label and on the safety data sheet (S.D.S).



CLIFTON

125 Kingsland Avenue
Clifton, NJ 07014
Tel.: 201-567-3000
Toll free: 1-800-631-1652

MONTREAL

10,900 Secant Street
Anjou, QC H1J 1S5
Tel.: 514-355-4660
Toll free: 1-800-361-8927

EDMONTON

11411-160 Street
Edmonton, Alberta T5M 3T7
Tel.: 780-454-3919
Toll free: 1-866-454-3919

United States
www.penetone.com

Canada
www.westpenetone.com