



PENETONE[®] 1112A

Multi Metal Safe Carbon Removing Compound

FEATURES/BENEFITS

Ready to use

Safe on most metals

Removes carbon

Mild odor

High flash point (> 210°F)

Penetone 1112A is available in 55 gallon drums and 6 gallon pails. Inquire about availability in other packages.

4345a.bul.wpd

(Mar04)

Description

Penetone 1112A is a ready-to-use carbon remover and aircraft thrust reverser, aft sleeve and bare metal component cleaner that has passed the effects on metals section of MIL-PRF-87937C. Designed to remove tough carbon deposits, *Penetone 1112A* will also remove enamel paints. Although designed as a ready-to-use product, *Penetone 1112A* can be used diluted.

Typical Use Directions (also see product label)

Carbon Removal: *Penetone 1112A* is ready to use. Do not add solvent or water. Fill cleaning bath to a reference mark with fresh compound. Before soaking item, remove loose grease, dirt and oil with a degreasing solvent. Place objects to be cleaned in a wire basket or hang them by a wire so as to be off the bottom and completely immersed. Soak for 2 to 16 hours as needed at temperatures up to 130°F and rinse with water or solvent. Brush with a stiff brush under hot water for complete removal.

Thrust Reverser, Aft Sleeve and Bare Metal Component Cleaning: Refer to directions in Technical Order 1C-135(K)A-3-4 or other applicable technical order. Use *Penetone 1112A* as supplied to 1:20 to remove soils. Apply by coarse spray or bucket and brush, agitate with abrasive pads and follow with a water rinse.

IMPORTANT: Before using *Penetone 1112A*, always be sure to read and follow warnings and directions for use appearing on the product container label and MSDS.