

MILITARY / COMMERCIAL AVIATION



Penair C5575 is low voc, heavy-duty cleaner that has been thickened in order to cling to vertical and overhead surfaces.

The thixotropic properties of **Penair C5575** allow it to be applied to soiled surfaces without product runoff.

This allows for an increased contact time, which results in better cleaning performance, decreased labor and reduced man-hour requirements.

Penair C5575 will not harm aircraft paints and is non-corrosive to aerospace metals.

FEATURES AND BENEFITS

- Thixotropic gel
- Less than 10% VOC
- Free rinsing
- Increased dwell time
- Excellent cleaning performance
- Leaves a residue-free surface
- Eliminates streaking
- Non-corrosive to aerospace metals

Use procedure

Apply **Penair C5575** using pressure spray (use coarse spray only), foam equipment, or bucket and brush.

Concentration

Use undiluted.

Dwell time/operation time

Allow product to dwell 5 to 15 minutes, brush if necessary, then spray with fresh water to rinse. Brush again.

Rinsing

Rinse again to completely remove cleaner.

PENAIR® C5575

EXTERIOR AIRCRAFT CLEANER, GEL TYPE DEGREASER

PHYSICAL PROPERTIES

Appearance	Clear to hazy, yellow-orange viscous liquid
Odor	Mild citrus
pH	About 9
Freezing Point	About 32°F
Boiling Point	About 212°F
Flash Point (TCC)	145°F
Relative Density	1.00
Auto-Ignition Temperature	Not determined
Water Solubility	Complete
Viscosity	Not determined (viscous shear thinning liquid)

INCOMPATIBILITY

Strong acids, bases or oxidizing agents.

WAREHOUSING PRECAUTIONS

Store in a well ventilated place. Keep cool. Keep container tightly closed when not in use. Do not store in direct sunlight. Avoid storing above 120°F (49°C).

AVAILABLE SIZES

5 gallon Pail

55 gallon Drum

APPROVALS

MIL-PRF-85570D Type V

AMS 1523B, Boeing D6-17487 Rev. P

Douglas Aircraft CSD-1

FIRST AID MEASURES

If in eyes: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. If eye irritation persists or develops: Get medical advice or attention. Penetone recommends that after any eye exposure a physician be seen immediately.

If swallowed: Rinse mouth. Call a poison center, doctor, physician or other competent medical authority if you feel unwell.

If inhaled: Remove person to fresh air and keep comfortable for breathing. Call a poison center, doctor, physician or other competent medical authority if you feel unwell.

If on skin: Wash with plenty of water or a mild soap. Take off contaminated clothing and wash it before reuse. If skin irritation or a rash occurs: Get medical advice or attention.

PERSONAL PROTECTION Security equipment



WHMIS



IMPORTANT: Before using **PENAIR C5575**, always be sure to read and follow precautions and directions for use appearing on the product container label and on the safety data sheet (S.D.S).



CLIFTON

125 Kingsland Avenue
Clifton, NJ 07014
Tel.: 201-567-3000
Toll free: 1-800-631-1652

MONTREAL

10,900 Secant Street
Anjou, QC H1J 1S5
Tel.: 514-355-4660
Toll free: 1-800-361-8927

EDMONTON

11411-160 Street
Edmonton, Alberta T5M 3T7
Tel.: 780-454-3919
Toll free: 1-866-454-3919

United States
www.penetone.com

Canada
www.westpenetone.com