

POWER CLEANER® 310 JET WASHER / ULTRASONIC CLEANER

GENERAL USE



FEATURES AND BENEFITS

- Biodegradable
- No solvents
- Safe on most metals
- Low foaming
- No phosphates
- Free rinsing
- Complies with Boeing BAC 5763 specification
- Ozone friendly
- Eliminates fire hazards
- Will not corrode or damage parts
- Eliminates record keeping and reporting of VOCs

DIRECTIONS FOR USE

Use procedures

Soils require soaking with 3-5 minute agitation. Tarnish removal from many alloys requires 10% or higher dilution ratio.

Note

Soft metal alloys such as aluminum, brass, bronze and copper may require lower temperatures and/or shorter contact times. Always pretest a small sample for compatibility under intended use conditions. Begin testing using low temperatures and low concentrations. Raise both until soil removal is complete and alloy remains unaffected.

PHYSICAL PROPERTIES

Appearance	Pale yellow liquid
Odor	Mild
рН	About 12
Freezing Point	About 25°F
Boiling Point	About 212°F
Flash Point (TCC)	Not applicable
Relative Density	1.14
Auto-Ignition Temperature	Not applicable
Water Solubility	Complete
Viscosity	Less than 5 CP at room temperature

INCOMPATIBILITY	
Strong acids.	
WAREHOUSING PRECAUTIONS	
Store locked up. Keep container tightly closed when not in use. Do not store in direct sunlight. Avoid storing above 120°F (49°C).	

APPROVALS

ASTM F519 BAC 5763 Rev D. Type II Class 1&2 Grades A&B

ASTM F945 ASTM F1110 (Sandwich corrosion of aluminum)

ARP 1755 GE CT 882 (includes some of above)

Hill AFB Wheel/Tire

FIRST AID MEASURES

If in eyes: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Immediately call a local Poison Control Center, doctor, physician or other competent medical authority for medical advice. Penetone recommends that after any eye exposure a physician be seen immediatelv.

If swallowed: Rinse mouth. DO NOT INDUCE VOMITING. Immediately call a poison center, doctor, physician or other competent medical authority for medical advice.

If inhaled: Remove person to fresh air and keep comfortable for breathing. Immediately call a local Poison Control Center, physician, or other competent medical authority for medical advice.

CARISTADT

700 Gotham Parkway

Carlstadt, NJ 07072

Tel.: 201-567-3000

If on skin (or hair): Take off immediately all contaminated clothing. Rinse skin with water or shower. A mild soap may be used to wash skin. Wash contaminated clothing before reuse. Immediately call a local Poison Control Center, doctor, physician or other competent medical authority for medical advice.

IMPORTANT: Before using POWER CLEANER 310, always be sure to read and follow precautions and directions for use appearing on the product container label and on the safety data sheet (S.D.S).



MONTRFAL

10,900 Secant Street Anjou, OC H1J 1S5 Tel.: 514-355-4660 Toll free: 1-800-631-1652 Toll free: 1-800-361-8927 Toll free: 1-866-454-3919

FDMONTON

11411-160 Street Edmonton, Alberta T5M 3T7 Tel.: 780-454-3919

WHMIS

United States www.penetone.com

Canada www.westpenetone.com

AVAILABLE SIZES

PERSONAL PROTECTION

Security equipment

5 gallon Pail

55 gallon Drum