

OIL & GAS FLUID TREATMENT



PENETONE 4038P is a hot watering additive designed to wet, soften, disperse, and inhibit or prevent wax deposition in well bores and in flowline batch treatments. **PENETONE 4038P** forms a temporary emulsion in most water sources and brines to effectively liquefy paraffin deposits and subsequently allow for phase separation to reclaim the water source or brine for continuous use. Additionally, the surfactant and PPD additives will reduce the effects of wax crystallization by reducing pour point and preventing further flow assurance issues.

FEATURES AND BENEFITS

- Fully active formulation
- Relies on the solvency and sustainability of d-limonene
- Contains active paraffin dispersant and pour point depressant
- Forms temporary emulsion for easy reclaim or recycling of water source or brine
- Rapidly blended into most water sources or brine
- Effective at low concentrations

DIRECTIONS FOR USE

Chemical type Solvent/surfactant/pour point depressant blend

Treatment rates Will vary depending on wax deposition, content, location, and situation. Optimization of the injections rates should be achieved through field testing.

Up to 3% v/v of the volume of water or brine being employed for hot watering or flowline batch treatments is recommended to achieve desired results.

PENETONE 4038P

PARAFFIN WAX DISPERSANT

PHYSICAL PROPERTIES

Appearance	Yellow liquid
Odour	Citrus / glycol
Specific Gravity @ 20°C	0.900-0.950
Viscosity	Thin
pH	6.50-7.00
Flash Point (TCC)	48°C
Boiling Point	Not determined
Freezing Point	Not determined
Foaming Tendency	Nil
Autoignition temperature	Not determined
Active content	100%
Water Solubility	Emulsifies

INCOMPATIBILITY

Oxidizing materials

WAREHOUSING PRECAUTIONS

Store away from heat sources and flames

AVAILABLE SIZES

			
20L	205L	1000L	

FIRST AID MEASURES

EYE CONTACT

Wash with plenty of water for 15 minutes. Consult physician if irritation develops or persists.

SKIN CONTACT

Wash with plenty of water for 15 minutes. Consult physician if irritation develops or persists.

INHALATION

Give fresh air or artificial respiration. Consult physician.

INGESTION

DO NOT induce vomiting. Drink plenty of water and contact physician immediately.

HEALTH

1

FLAMMABILITY

2

REACTIVITY

0

LEGEND

0 = MINIMAL RISK
1 = SLIGHT RISK
2 = MODERATE RISK
3 = SERIOUS RISK
4 = SEVERE RISK

PERSONAL PROTECTION Security equipment



WHMIS



IMPORTANT: Before using PENETONE 4038P, always be sure to read and follow precautions and directions for use appearing on the product container label and on the safety data sheet (S.D.S).



CLIFTON

125 Kingsland Avenue
Clifton, NJ 07014
Tel.: 201-567-3000
Toll free: 1-800-631-1652

MONTREAL

10,900 rue S e cant
Anjou, Q uebec H1J 1S5
Tel.: 514-355-4660
Toll free: 1-800-361-8927

EDMONTON

11411-160 Street
Edmonton, Alberta T5M 3T7
Tel.: 780-454-3919
Toll free: 1-866-454-3919

United States
www.penetone.com

Canada
www.westpenetone.com