

GENERAL USE



PENMUL L950 is an odorless solvent emulsion degreaser designed to remove quickly most soils as well as oily or greasy substances from metal, wood, plastic, painted, coated or fabric surfaces. It is completely neutral (nonacidic, nonalkaline).

Formulated with powerful, odorless solvents and concentrated chemical emulsifiers, **PENMUL L950** quickly dissolves and emulsifies grease and oil, light carbonaceous deposits and tar-like substances which can easily be rinsed away with water, without leaving an oily film or strong obnoxious odor.

FEATURES AND BENEFITS

- Low odor
- Slow evaporation
- Easily rinsed with hot, cold, fresh or sea water
- High flash point

DIRECTIONS FOR USE

Use procedures

Penmul L950 is generally used concentrated in wipe, dip or non-atomizing coarse spray applications. Apply to part to be cleaned and allow to set for several minutes then hose down with water. **Penmul L950** may be diluted with water prior to use.

PENMUL L950

HIGH POWERED DEGREASER, ASPHALT REMOVER

PHYSICAL PROPERTIES

Appearance	Clear liquid
Odor	Mild hydrocarbon
pH	Not applicable
Freezing Point	Not determined
Boiling Point	Not determined
Flash Point	155°F TCC, 170°F COC
Relative Density	0.81
Auto-Ignition Temperature	about 450°F
Water Solubility	Emulsifies
Viscosity	Less than 5 CP at room temperature

INCOMPATIBILITY

Strong oxidizing agents.

WAREHOUSING PRECAUTIONS

Store in a well-ventilated place. Keep container tightly closed. Open slowly in order to control possible pressure release. Keep cool. Store locked up. Do not store near heat, sparks, open flame, or other ignition sources. Do not store in direct sunlight. Avoid storing above 120°F (49°C).

AVAILABLE SIZES

5 gallon Pail

55 gallon Drum

FIRST AID MEASURES

If in eyes: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. If eye irritation persists or develops: Get medical advice or attention. Penetone recommends that after any eye exposure a physician be seen immediately.

If swallowed: Immediately call a poison center, doctor, physician or other competent medical authority. Rinse mouth. Product presents an aspiration hazard. DO NOT INDUCE VOMITING.

If inhaled: Remove person to fresh air and keep comfortable for breathing. Call a poison center, doctor, physician or other competent medical authority if you feel unwell.

If on skin (or hair): Take off immediately all contaminated clothing. Rinse skin with water or shower. A mild soap may be used to wash skin. Wash contaminated clothing before reuse. If skin irritation or rash occurs: Get medical advice or attention.

PERSONAL PROTECTION Security equipment



WHMIS



IMPORTANT: Before using **PENMUL L950**, always be sure to read and follow precautions and directions for use appearing on the product container label and on the safety data sheet (S.D.S).



CLIFTON

125 Kingsland Avenue
Clifton, NJ 07014
Tel.: 201-567-3000
Toll free: 1-800-631-1652

MONTREAL

10,900 Secant Street
Anjou, QC H1J 1S5
Tel.: 514-355-4660
Toll free: 1-800-361-8927

EDMONTON

11411-160 Street
Edmonton, Alberta T5M 3T7
Tel.: 780-454-3919
Toll free: 1-866-454-3919

United States
www.penetone.com

Canada
www.westpenetone.com