

GENERAL USE



Power Cleaner is a highly concentrated, liquid alkaline, low foaming detergent for use in manual application, power sprayers, and in steam cleaning and power scrubbing equipment.

FEATURES AND BENEFITS

- Non-flammable
- Evaporates quickly
- Leaves no residual film
- Non-corrosive
- Restores electrical continuity
- Non-conductive
- 24 KV Dielectric strength
- 1,1,1 Replacement
- Non ozone depleting
- No SARA title III reportables
- Non-carcinogenic

DIRECTIONS FOR USE

Use procedures

SURFACES	SOILS	ONCES/WATER GALLON
GENERAL SURFACE CLEANING - Floors, walls, equipment		
Oil sump areas, pits, walls, machine frames, bases, housings	Heavy grease, oils, grime	4 - 8
Garage floors, walls, heavy equipment	Greases, oils, dirt, grime	2 - 4
General maintenance - floors, walls, metal equipment	Dirt, grime, oils, wax buildup	1 - 4
Converter Industry - analox system (flush), top print & bottom rollers, outside flexographic equipment, rubber dyes, floors	Water-based paints & inks, machine oils, grease, dirt	10 - 16
Painted walls	Dirt, grime & soot buildup, hand marks	1/2 - 1
STEAM CLEANING (Note: Wear appropriate face mask)		
Floors, walls, steel equipment	Heavy buildup of oils & greases, soot	4 - 8
Metal dies, painted equipment, floors, walls	Light buildup of oils, greases, grime, releasing agents	1 - 4
Metal stock parts, tools	Light protective oils, water-based coatings	3 - 5
POWER SPRAYING (Use only coarse non-vaporizing spray)		
Walls & floors	Heavy greases, oils, water based ink or paint spills	4 - 6
Equipment	Light to medium soils, soot buildup	2 - 4
POWER SCRUBBING		
Floor surfaces & concrete	Heavy ground-in dirt, grime, soot, oil, grease, ink spills	3 - 4

POWER CLEANER®

LOW FOAMING MULTIPURPOSE CLEANER

PHYSICAL PROPERTIES

Appearance	Clear liquid
Odor	Mild
pH	>12.5
Freezing Point	About 32°F
Boiling Point	About 212°F
Flash Point (TCC)	Not applicable
Relative Density	1.17
Auto-Ignition Temperature	Not applicable
Water Solubility	Complete
Viscosity	Less than 5 CP at room temperature

INCOMPATIBILITY

Strong acids.

WAREHOUSING PRECAUTIONS

Store locked up. Keep container tightly closed when not in use.
Do not store in direct sunlight.
Avoid storing above 120°F (49°C).

AVAILABLE SIZES

4 X 1 gallon

5 gallon Pail

55 gallon Drum

FIRST AID MEASURES

If in eyes: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Immediately call a local Poison Control Center, doctor, physician or other competent medical authority for medical advice. Penetone recommends that after any eye exposure a physician be seen immediately.

If swallowed: Rinse mouth. DO NOT INDUCE VOMITING. Immediately call a poison center, doctor, physician or other competent medical authority for medical advice.

If inhaled: Remove person to fresh air and keep comfortable for breathing. Immediately call a local Poison Control Center, physician, or other competent medical authority for medical advice.

If on skin (or hair): Take off immediately all contaminated clothing. Rinse skin with water or shower. A mild soap may be used to wash skin. Wash contaminated clothing before reuse. Immediately call a local Poison Control Center, doctor, physician or other competent medical authority for medical advice.

PERSONAL PROTECTION Security equipment



WHMIS



IMPORTANT: Before using **POWER CLEANER**, always be sure to read and follow precautions and directions for use appearing on the product container label and on the safety data sheet (S.D.S).



CLIFTON

125 Kingsland Avenue
Clifton, NJ 07014
Tel.: 201-567-3000
Toll free: 1-800-631-1652

MONTREAL

10,900 Secant Street
Anjou, QC H1J 1S5
Tel.: 514-355-4660
Toll free: 1-800-361-8927

EDMONTON

11411-160 Street
Edmonton, Alberta T5M 3T7
Tel.: 780-454-3919
Toll free: 1-866-454-3919

United States
www.penetone.com

Canada
www.westpenetone.com